

TERMOSTATO LINK





08540010
08540050
08540090
08540020
08540060
08540100




www.griferiarovira.com

1







2



Min. = 27mm
Max. = 67mm

3x




1 MÍN
5 MÁX

1 A 3 BAR

50 °
80 °

50° A 65°



> 5 BAR



❄ - ☀ ≤ 1,5 BAR


El incumplimiento de estas instrucciones exime de toda responsabilidad a Grifería Sanitaria Rovira s.a.

Griferia Sanitaria Rovira s.a. shall not be held liable for the non-compliance of these instructions.








Le non-respect de ces instructions exonère a Griferia Sanitaria Rovira s.a. de toute responsabilité.

3


08540010 08540050 08540090



08540020 08540060 08540100



4





5


IMPRESINDIBLE Y OBLIGATORIO VERIFICAR LA ESTANQUEIDAD Y EL CORRECTO FUNCIONAMIENTO DE LA PIEZA ANTES DE PONER EL REVESTIMIENTO.

VERIFYING TIGHTNESS AND CORRECT PERFORMANCE OF THE PIECE BEFORE TILING IS INDISPENSABLE AND COMPULSORY.




IL EST INDISPENSABLE ET OBLIGATOIRE DE VÉRIFIER L'ÉTANCHEITÉ ET LE BON FONCTIONNEMENT DE LA PIÈCE AVANT DE POSER LE REVÊTEMENT.




1




2







3



4



5



OK



